



INTAKE RUBBER 1000ER BOXER



10,32€

38240-000. Old, brittle intake rubbers are often the main culprits for air leaks and an unsound running engine. If in doubt do always change these rubbers as soon as any signs of wear occur.

SKU: 38240-000